	1	
	ı	

	TOTAL BILL OF MATERIAL																						
BRIDGE NO.	GROOVING BRIDGE FLOORS	CLASS AA CONCRETE	REINFORCING STEEL	CLASS II, SURFACE PREPARATION	CLASS III, SURFACE PREPARATION	LATEX MODIFIED CONCRETE OVERLAY	PLACING & FINISHING OF LATEX MODIFIED CONC OVERLAY	SHOTCRETE REPAIRS	CONCRETE REPAIRS	EPOXY RESIN INJECTION	FOAM JOINT SEALS	CLEANING & REPAINTING OF BRIDGE #_	PAINTING CONTAINMENT FOR BRIDGE #_	POLLUTION CONTROL	ELASTOMERIC CONCRETE	BEAM REPAIR	EPOXY COATING	BRIDGE JOINT DEMOLITION	SCARIFYING BRIDGE DECK	HYDRO- DEMOLITION OF BRIDGE DECK	STEEL KEEPER ANGLE ASSEMBLY	ANCHOR BOLT REPAIR	BRIDGE JACKING
	SQ.FT.	CU. YDS.	LBS.	SQ. YDS.	SQ. YDS.	CU. YDS.	SQ. YDS.	CU.FT.	CU.FT.	LIN.FT.	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	CU.FT.	LBS.	SQ.FT.	SQ.FT.	SQ. YDS.	SO. YDS.	EA.	EA.	EA.
183		—						180.7	70.9	129.5		LUMP SUM	LUMP SUM	LUMP SUM		1 *	714					6	9
205								21.3		24.0													_
208								24.7		142.8													
209	4,280	3.8	320	4.7		29.0	515	20.5		5.6	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	21.0			40	515	515			
222	4,280	3.8	320	0.2		28.7	515	33.6		15.8	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	21.0			40	515	515			
223	5,178	6.0	366	25.0	8.8	36.6	623	40.9		5.0	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	24.4	_		46	623	623			
224	5,178	4.8	366	12.4	2.3	35 <b>.</b> 6	623	71.7		3 <b>.</b> 5	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	24.4			46	623	623			
228	17,526			1.8		117.5	2,114	634.3	62.3	41.4	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	40.0	50	656	160	2,114	2,114	4		4
230	17,526	_		11.1		118.2	2,114	493.2		70.0	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	40.0	45	656	160	2,114	2,114			
231	5 <b>,</b> 610	4.6	332			37 <b>.</b> 5	676	8.0	17.8		LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	22.0			42	676	676			
232	5 <b>,</b> 610	4.6	332	2.1		37.7	676	6.4		7.6	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	22.0			42	676	676			
TOTAL	65,188	27.6	2,036	57.3	11.1	440.8	7,856	1,535.3	151.0	445.2	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	214.8	96 *	2,026	576	7,856	7,856	4	6	13

\* THE FLANGE REPAIR ON BRIDGE NO.183 WILL BE INCLUDED IN THE UNIT CONTRACT PRICE BID FOR "BEAM REPAIR". A TOKEN QUANTITY IS REPORTED ON THE TOTAL BILL OF MATERIAL.

◆ QUANTITY HAS BEEN INCREASED DUE TO THE POTENTIAL FOR FURTHER DETERIORATION SINCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT.

PROJECT NO. I-5756
HAYWOOD COUNTY

BRIDGE NO. 183, 205, 208, 209, 222, 223, 224, 228, 230, 231, 232

Docusigned by:

John J. Habelman COM

7BC36E9CE 29 FESSION

SEAL

32492

4/5/2016

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

TOTAL BILL OF MATERIAL

REVISIONS SHEET NO.

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 SHEET NO. BY: DATE: SHEET'S SHEET NO. BY: DATE: NO. BY: DATE: NO. BY: DATE: SHEET'S SHEET

 DRAWN BY:
 J. YANNACCONE
 DATE:
 10/15

 CHECKED BY:
 S. WANCE
 DATE:
 1/16